


IMPROVEMENTS TO THE SUPPORT KIT AND PROFILE FOR AIR CONDITIONER 550

- 1 Hole on the top part for better bracket fixation
- 2 Longitudinal reinforcement ribs in the adjustment bar
- 3 Reinforcement ribs on the sides of the bracket
- 4 Larger size for better reinforcement
- 5 Wider base (45 mm)
- 6 Longer vertical part of the bracket (400 mm)
- 7 Additional holes 80x10.5 for better adjustment

Note: larger universal wall plugs, Ref No: 2411200000





IMPROVEMENTS TO THE SUPPORT KIT AND PROFILE FOR AIR CONDITIONERS 420 AND 460

- 1 Hole on the top part for better bracket fixation
- 2 Longitudinal reinforcement ribs in the adjustment bar
- 3 Reinforcement ribs on the sides of the bracket
- 4 Larger size for better reinforcement
- 5 Wider base (45 mm)
- 6 Longer vertical part of the bracket (400 mm)

Note: larger universal wall plugs, Ref No: 2411200000

